



JON M. HUNTSMAN, JR.  
Governor  
GARY R. HERBERT  
Lieutenant Governor

**State of Utah**  
**DEPARTMENT OF NATURAL RESOURCES**  
**Division of Oil, Gas & Mining**

MICHAEL R. STYLER      JOHN R. BAZA  
Executive Director      Division Director

**Inspection Report**  
**Minerals Regulatory Program**  
November 1, 2005

Supervisor ORZ

**Mine Name:** Highland Mist  
**Operator Name:** Anasazi Gold Reserves  
c/o North American Exploration  
447 North 300 West Suite 3  
Kaysville, Utah 84037-4203

**Permit number:** S/021/035  
**Inspection Date:** October 28, 2005  
**Time:** 8:30 AM

**Inspector(s):** Doug Jensen  
**Other Participants:** None  
**Mine Status:** Active

**Weather:** Cool, rainy

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

**Purpose of Inspection:**  
Checking the site for activity.

**Inspection Summary:**  
Development activity has been initiated at the site since my last visit on April 25, 2005.

5. Roads (maintenance, surfacing, dust control, safety)  
A ~25' wide road has been constructed running from the highway to the upper disturbance. The operator has removed material from a drainage which runs alongside the road. It appears that they plan on using this material for road base on the newly constructed road. Three pads have been developed along the length of the road, possibly for stockpiling material removed during any future mining operation.

12. Other  
A harvester is parked just inside the fence on the permit area. There is other equipment located just across the highway on a piece of fee land. It is assumed that the equipment parked in this area also belongs to Anasazi Gold. Other than the harvester there was no other equipment located on the permit area. The dozer and trackhoe used to make the disturbances on the permit did not appear to still be in the area on either side of the highway.

Inspection Date: October 28, 2005; Report Date: November 1, 2005  
Page 2 of 2  
S/021/035

On the lower site a cut and fill road has been pioneered on the hillside above a rock outcrop. The road is fairly steep with 22 locations marked down the center. It is assumed that these will be future drill hole locations. There were no other signs of work being done in this area.

An additional development has also been started on the upper site of the permit where about a quarter of an acre disturbance has been made. A dozer was used to remove the nose of a hill and a small dump area formed on the lower side of this disturbance where the material from the cut has been pushed. It does not appear that any of this material has been removed from the site.


A GPS map was made of the road disturbances was made while I was onsite.

There was no other evidence of activity at the site.

**Conclusions and Recommendations:**

I will continue to monitor the site when I am in the area.

**Inspector's Signature**



**Date:** November 1, 2005

dj:jb

cc: Anasazi Gold Reserves, Operator  
Will Stokes (ML 49111)

Attachment: GPS

O:\M021-Iron\S0210035-HighlandMist\inspections\10282005insp.doc



Mine Number: S0210035  
Mine Name: Highland Mist  
Township 32 S Range 05.5 W Section 36 SLBM

Inspection Date Oct. 28, 2005  
Map Produced by DKS

Acres Disturbed	0
Acres Regraded	0
Acres Seeded	0
Road Acres Disturbed	0.8
Total Acres Disturbed	0.8
Acres Released	0
Acres Excluded	0
Acres PreExisting	0
Acres Prelaw	0

**Legend**  
All items symbolized in legend may not be appear on map

County Boundary

Access

Mine

NonMine

Other

Interstate

US Route

State Route

Primary Route

Secondary Route

Main Dirt Road

Unimproved Road

Interchange

Trail

Township or range line

Township or range line: location doubtful

Section line

Section line: location doubtful

Disturbed

Regraded

Seeded

Released

Excluded

PreExisting

Prelaw


Bond Area

SITLA Mineral Leases

BLM State Minerals

Community Pit

DOQ imagery date 2004



N

W

E

S

0 625 Feet

1:7,500 1 inch equals 625 feet

Verify Scale

Dept. of Natural Resources  
Division of Oil, Gas, and Mining  
Mineral Mines Program

Different data sources and input scales  
may cause misalignment of data layers.  
This product may not meet DOGM  
standards for accuracy and content.

